JOSEPH P. BILECKI LAND SURVEYOR

221 Matty Ave.

Phone 455-1169

August 28, 1970

Subject: Sanitary Fill Area in Town of Salina

Location: Bounded - North by Ley Creek South by Penn Central RR.

Edat by Route #11 West by Crouse Hinds Property

East

Elevations:

- 1 Center line pavement 7th North St. Center line entrance road to fill area Assumed elevation - 100.0
- 2 Ley Creek station 18/00 Top covered fill - 101.0
- 3 Covered fill south of entrance road north of wood power pole line - 104.8
- 4 Uncovered fill north of entrance road south of Ley Creek - 106.8
- 5 Uncovered fill north of Penn Central RR. south of wood power pole line 103.8
- 6 Uncovered fill area in operation east end of sanitary fill area nearest Route #11 107.3
- 7 Center line pavement Route #11 opposite end of east wing wall RR bridge 104.84

Elevations at 2-3-4-5 in area lying about midway between 7th North St. and Route #11

Observations - No evidence of sand bank fill along Ley Creek or established bench marks to control elevations.

Joseph P. Bilecki - L. S. 31722

/s/ Joseph P. Bilecki

JOSEPH P. BILECKI LAND SURVEYOR

221 Matty Ave.

Phone 455-1169

August 28, 1970

Subject: Sanitary Fill Area in Town of Salina

Location: Bounded - North by Ley Creek South by Penn Central RR.

Edat by Route #11 West by Crouse Hinds Property

Elevations:

- 1 Center line pavement 7th North St. Center line entrance road to fill area Assumed elevation - 100.0
- 2 Ley Creek station 18/00 Top covered fill - 101.0
- 3 Covered fill south of entrance road north of wood power pole line - 104.8
- 4 Uncovered fill north of entrance road south of Ley Creek - 106.8
- 5 Uncovered fill north of Penn Central RR. south of wood power pole line 103.8
- 6 Uncovered fill area in operation east end of sanitary fill area nearest Route #11 107.3
- 7 Center line pavement Route #11 opposite end of east wing wall RR bridge 104.84

Elevations at 2-3-4-5 in area lying about midway between 7th North St. and Route #11

Observations - No evidence of sand bank fill along Ley Creek or established bench marks to control elevations.

Joseph P. Bilecki - L. S. 31722

/s/ Joseph P. Bilecki